

**From:** [Nejand, Patrick C CIV USARMY CENAN \(USA\)](#)  
**To:** [Hauber, Erin M CIV USARMY CENWK \(USA\)](#); [Granger, Michelle](#); [Kolb, Neal F CIV USARMY CENAN \(USA\)](#); [rich.e.gajdek@usace.army.mil](mailto:rich.e.gajdek@usace.army.mil)  
**Cc:** [Nanci Higginbotham](#); [Brink, Bradley J CIV USARMY CENWK \(USA\)](#)  
**Subject:** Pohatcong OU3 PVGCS OU3 for Sunday 22 December 2019 Drilling operations (HF8-9 in former molding room / Production Room drilling setup)  
**Date:** Monday, December 30, 2019 12:01:29 AM  
**Attachments:** [Pohatcong OU3 PVGCS OU3 PRP Oversight 20191222 r1.pdf](#)  
[Pohatcong OU3 HF8-9 drilling 22DEC2019.jpg](#)  
[Pohatcong Ou3 SB 35 Location 22DEC2019 IMG\\_0571.jpg](#)  
[Pohatcong OU3 TRS cleaning in Mechanical room 22DEC2019.jpg](#)

---

Michelle / Erin,

Please find attached the daily report for Sunday 22DEC2019 for Pohatcong OU3. Ramboll / GSE had continued drilling in former molding room. Pratt had set-up in the production room. Ramboll to monitor with regard to potential seepage of drilling fluid water/mud into other areas when GSE is drilling close to potential plant work areas when GSE returns on 06JAN2020. Thank you.

Patrick  
Cell. No. 732-501-2729